# PATENT ABSTRACTS OF JAPAN

(11)Publication number:

10-180623

(43) Date of publication of application: 07.07.1998

(51)Int.CI.

B24B 37/04

(21)Application number : 08-358296

(71)Applicant: MITSUBISHI MATERIALS

SHILICON CORP

MITSUBISHI MATERIALS CORP

(22)Date of filing:

26.12.1996

(72)Inventor: FUJIWARA SUSUMU

**TATSUTA JIRO** 


KITAMURA YOSHIKI SUGITANI KAZUAKI

# (54) LAPPING DEVICE

(57)Abstract:

PROBLEM TO BE SOLVED: To prevent a water from being scratched at its underside or being cracked in the lapping.

SOLUTION: Each carrier 13 is perforated with a plurality of through holes 19 in its thickness direction. The total opening area of the through holes 19 is set between 0.8% and 20% of the whole surface area of the carrier 13. Slurry is fed through the through holes 19 to the underside of wafers 14. Opening area ratios below 0.8% insufficiently feed slurry to the underside of the wafers 14, causing scratches on their underside, while those over 20% lower the mechanical strength of the carrier 13, resulting in an imperfect hold of the wafers 14 and thus their cracks.



The opening area of each through hole 19 is preferably not larger than 60cm2. The plural through holes 19 are dispersively formed over the whole surface of the carrier 13 in a uniform way. The slurry used in the lapping includes FO. That arrangement prevents scratches on the wafers 14 and their cracks.

#### LEGAL STATUS

[Date of request for examination]

30.03.2001

[Date of sending the examiner's decision of

01.04.2004

rejection]

[Kind of final disposal of application other than the examiner's decision of rejection or application converted registration]

[Date of final disposal for application]

[Patent number]

[Date of registration]

[Number of appeal against examiner's decision of rejection]

[Date of requesting appeal against examiner's decision of rejection]

[Date of extinction of right]

Copyright (C); 1998,2003 Japan Patent Office

JPO and NCIPI are not responsible for any damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.\*\*\*\* shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

#### **CLAIMS**

[Claim(s)]

[Claim 1] Wrapping equipment which formed the gangway penetrated in the vertical direction on the above-mentioned carrier in the wrapping equipment with which it intervenes between the lower lapping plates and top boards which were mutually prepared in parallel, and these top boards and lower lapping plates, and has a carrier holding a wafer, and a slurry is supplied from the upper part of a carrier.

[Claim 2] The above-mentioned gangway is wrapping equipment according to claim 1 which is two or more holes formed in abbreviation homogeneity by being distributed on the front face of the above-mentioned carrier.

[Claim 3] The above-mentioned hole is wrapping equipment according to claim 2 which has 0.8 - 20% of opening area to the total surface area of a carrier.

JPO and NCIPI are not responsible for any damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.\*\*\*\* shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

#### DETAILED DESCRIPTION

[Detailed Description of the Invention]

[0001]

[Field of the Invention] This invention relates to amelioration of the wrapping equipment used for wrapping of a silicon wafer etc., especially the wrapping equipment which wraps wafer both sides simultaneously.

[0002]

[Description of the Prior Art] This conventional kind of wrapping equipment was a configuration to wrap, having inserted and held the wafer at the carrier and supplying a slurry to a wafer from that upper part. That is, the carrier was formed free [ rotation and revolution ] between the sun gear and flywheel starter gear which were prepared free [ a revolution ], and wrapping processing had been performed by pressing and \*\*\*\*ing the table rear face (vertical side) of the wafer held on this carrier by the top board and the lower lapping plate. And the slurry was supplied to the carrier top face in [ hole / which was formed in the top board ] this case.

[0003]

[Problem(s) to be Solved by the Invention] However, if it is in such conventional wrapping equipment, since the breakthrough is not formed in this carrier other than the hole holding a wafer, a slurry is a pile to a surroundings lump in the wafer bottom. That is, with conventional wrapping equipment, during lap processing, although a slurry is enough supplied to a wafer top face since a slurry is supplied from the upper part of a carrier, the underside is hard to be supplied. Consequently, the technical problem that it was easy to generate a scratch on the wafer underside had arisen. [0004]

[Objects of the Invention] This invention sets it as that object to offer the wrapping equipment which abolished scratch generating under a wafer. Moreover, this invention sets it as that object to offer wrapping equipment without the crack of the wafer in wrapping processing.

[Means for Solving the Problem] Invention according to claim 1 is the wrapping equipment in which the gangway penetrated in the vertical direction on the above-mentioned carrier was formed, in the wrapping equipment with which it intervenes between the lower lapping plates and top boards which were mutually prepared in parallel, and these top boards and lower lapping plates, and has a carrier holding a wafer, and a slurry is supplied from the upper part of a carrier.

[0006] Invention according to claim 2 is wrapping equipment according to claim 1 which is two or more holes formed by distributing the above-mentioned gangway over abbreviation homogeneity on the front face of the above-mentioned carrier.

[0007] Invention according to claim 3 is wrapping equipment according to claim 2 with which the above-mentioned hole has 0.8 - 20% of opening area to the total surface area of a carrier. [0008]

[Function] In invention according to claim 1, a slurry is supplied from the upper part of a carrier at the time of lap processing. This slurry is supplied to the underside of the lower part of a carrier, i.e., the wafer to hold, through a gangway. Consequently, the slurry of amount sufficient between a wafer underside and a lower lapping plate can be supplied, and generating of a scratch can be avoided thoroughly.

[0009] In claim 2 and invention according to claim 3, a slurry is supplied from the upper part of a

carrier at the time of lap processing. This slurry is fully supplied to the underside of the wafer held through two or more holes. Therefore, scratch generating can be prevented. Moreover, the opening area of two or more holes can be written among 0.8 - 20% to the total surface area of a carrier, and the mechanical strength of the carrier itself can also be held. And a crack does not arise to the wafer held at the carrier. For example, when a hole is formed exceeding 20%, it may be in the condition of the lack of a mechanical strength of a carrier, and while the carrier itself wraps, it may deform, and a crack may arise to a wafer. Moreover, the amount of supply of the slurry to an underside is not enough in this value being less than 0.8%, and it is because the problem of a scratch arises. The total surface area of a carrier means the area of the whole top face of a carrier including the hole for wafer maintenance here. When are put in another way, and the radius of a carrier is set to r and total surface area is set to S, it has the relation of S=pi r2.

[Embodiment of the Invention] Hereafter, one example of this invention is explained with reference to a drawing. <u>Drawing 1</u> - <u>drawing 3</u> are drawings showing one example of the wrapping equipment concerning this invention. <u>Drawing 4</u> and <u>drawing 5</u> are graphs which show the relation between the opening area (pair carrier all surface area ratio) of a breakthrough, and the crack of a wafer and scratch generating to a wafer.

[0011] As shown in these <u>drawing 1</u> - <u>drawing 3</u>, this double-sided wrapping equipment has the sun gear 11 prepared in the circumference of a shaft free [ a revolution ], this shaft and the flywheel starter gear 12 prepared free [ a revolution ] in same axle, and the tabular circular carrier 13 which engages simultaneously on both these gears 11 and 12, and revolves around the sun and rotates on them. More than one are arranged in the surroundings of sun gear 11, four silicon wafers 14 are inserted in each carrier 13 in the hole, and the carrier 13 is held, respectively.

[0012] A top board 15 and a lower lapping plate 16 will be arranged in the upper and lower sides of each carrier 13 by this and parallel, and the table rear face (vertical side) will be wrapped to each wafer 14 by supplying a slurry among these top boards 15 and lower lapping plates 16, and carriers 13. That is, two or more gangways 17 are formed in the top board 15, and it is constituted so that the slurry from a supply source may be supplied between the underside of a top board 15, and carrier 13 top face from these gangways 17. In addition, as shown in <u>drawing 2</u>, the slot 18 (for example, the flute width of 2mm, the channel depth of 10mm) is formed in each lap side of these top boards 15 and a lower lapping plate 17.

[0013] And it is in the wrapping equipment concerning the above-mentioned configuration, and two or more breakthroughs 19 which penetrate this in the thickness direction (in the vertical direction) are formed in the above-mentioned carrier 13. The full admission opening area of these breakthroughs 19 is set up so that it may become 0.8% - 20% to the total surface area of a carrier 13. It is because a scratch occurs on the underside as less than 0.8% of the amount of supply to wafer 14 underside of a slurry is insufficient and it is shown in drawing 5. Moreover, when a breakthrough 19 is formed exceeding 20%, the mechanical strength of carrier 13 the very thing is insufficient, maintenance of a wafer 14 is not perfect, and it is because there is a possibility that a crack may arise to a wafer 14. The relation between the opening area of a breakthrough 19 and the crack of a wafer 14 is shown in drawing 4. In addition, it is suitable for the opening area of one breakthrough that it is [60cm] two or less. Moreover, two or more breakthroughs shall be distributed and formed in homogeneity to the whole carrier surface. The slurry which contains a well-known thing (FO), for example, compound artificial emery etc., as a slurry used for wrapping is used.

[0014] <u>Drawing 4</u> is drawing showing the relation between the ratio which the full admission opening area of the above-mentioned breakthrough 19 occupies to the total surface area of a carrier 13, and the outbreak of the wafer in wrapping using this carrier 13 of a crack. In this wrapping, the slurry which contains compound artificial emery (FO#1200) as a wrapping abrasive grain was used with the wrapping equipment which used the carrier made of cast iron. The silicon wafer of the diameter of 8 inch was wrapped, and the crack was observed visually.

[0015] <u>Drawing 5</u> is drawing showing the relation between the ratio which the full admission opening area of the above-mentioned carrier occupies to the total surface area of a carrier, and the outbreak of a scratch under [ in wrapping using this carrier ] a wafer. Specifically, the 8 inch wafer was wrapped as well as the case of above-mentioned <u>drawing 4</u> using the carrier made of cast iron by

using compound artificial emery (FO#1200) as a wrapping abrasive grain. The scratch of the wafer side as the result was observed visually. If scratch generating increases [ the opening area of the breakthrough 19 formed in the carrier ] at less than 0.8% and 20% is exceeded as shown in these drawing 4 and drawing 5, the crack incidence rate of a wafer will become high. [0016]

[Effect of the Invention] According to this invention, in wrapping processing, it is hard to generate a scratch on the wafer underside. Moreover, a crack does not arise to a wafer.

JPO and NCIPI are not responsible for any damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.\*\*\*\* shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

#### DESCRIPTION OF DRAWINGS

[Brief Description of the Drawings]

[Drawing 1] It is the perspective view fracturing and showing some wrapping equipments concerning one example of this invention.

[Drawing 2] It is drawing of longitudinal section showing the wrapping equipment concerning one example of this invention.

[Drawing 3] It is the top view showing the carrier of the wrapping equipment concerning one example of this invention.

[Drawing 4] It is the graph which shows the relation of the opening area of the carrier breakthrough in wrapping equipment and the crack of a wafer concerning one example of this invention.

[Drawing 5] It is the graph which shows the relation of the opening area of the carrier breakthrough in wrapping equipment and the scratch incidence rate of a wafer concerning one example of this invention.


[Description of Notations]


- 13 Carrier,
- 14 Silicon Wafer,
- 15 Top Board,
- 16 Lower Lapping Plate,
- 17 Gangway.


JPO and NCIPI are not responsible for any damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.\*\*\* shows the word which can not be translated.
- 3.In the drawings, any words are not translated.


## **DRAWINGS**








[Drawing 3]





# PATENT ABSTRACTS OF JAPAN

(11)Publication number:

10-180623

(43)Date of publication of application: 07.07.1998

(51)Int.CI.

B24B 37/04

(21)Application number: 08-358296

(71)Applicant:

MITSUBISHI MATERIALS SHILICON CORP

MITSUBISHI MATERIALS CORP

(22)Date of filing:

26.12.1996

(72)Inventor:

**FUJIWARA SUSUMU** 


TATSUTA JIRO KITAMURA YOSHIKI SUGITANI KAZUAKI

## (54) LAPPING DEVICE

(57)Abstract:

PROBLEM TO BE SOLVED: To prevent a water from being scratched at its underside or being cracked in the lapping.

SOLUTION: Each carrier 13 is perforated with a plurality of through holes 19 in its thickness direction. The total opening area of the through holes 19 is set between 0.8% and 20% of the whole surface area of the carrier 13. Slurry is fed through the through holes 19 to the underside of wafers 14. Opening area ratios below 0.8% insufficiently feed slurry to the underside of the wafers 14, causing scratches on their underside, while those over 20% lower the mechanical strength of the carrier 13, resulting in an imperfect hold of the wafers 14 and thus their cracks. The opening area of each through hole 19 is preferably not larger than 60cm2. The plural through holes 19 are dispersively formed over the whole surface of the carrier 13 in a uniform way. The slurry used in the lapping includes FO. That arrangement prevents scratches on the wafers 14 and their cracks.



#### **LEGAL STATUS**

[Date of request for examination]

30.03.2001

[Date of sending the examiner's decision of rejection]

01.04.2004

[Kind of final disposal of application other than the examiner's decision of rejection or application converted registration]

[Date of final disposal for application]

[Patent number]

[Date of registration]

[Number of appeal against examiner's decision of rejection]

[Date of requesting appeal against examiner's decision of rejection]

[Date of extinction of right]

Copyright (C); 1998,2003 Japan Patent Office

# (19)日本国特許庁 (JP) (12) 公開特許公報 (A)

### (11)特許出願公開番号

# 特開平10-180623

(43)公開日 平成10年(1998)7月7日

(51) Int.Cl.<sup>6</sup>

識別記号

FΙ

B 2 4 B 37/04

B 2 4 B 37/04

С

# 審査請求 未請求 請求項の数3 FD (全 4 頁)


(21)出願番号	特顧平8-358296	(71) 出願人	000228925
			三菱マテリアルシリコン株式会社
(22)出顯日	平成8年(1996)12月26日		東京都千代田区大手町一丁目5番1号
		(71)出顧人	000006264
			三菱マテリアル株式会社
			東京都千代田区大手町1丁目5番1号
		(72)発明者	藤原 進
			東京都千代田区大手町1丁目5番1号 三
			菱マテリアルシリコン株式会社内
		(72)発明者	龍田 次郎
	•		東京都千代田区大手町1丁目5番1号 三
			菱マテリアルシリコン株式会社内
		(74)代理人	
			最終頁に続く

### (54) 【発明の名称】 ラッピング装置

#### (57)【要約】

【課題】 ラッピングでのウェーハ下面のスクラッチ発 生をなくす。ラッピング加工でのウェーハの割れを防止 する。

【解決手段】 キャリア13にその厚さ方向に貫通する 貫通孔19を複数個形成する。貫通孔19の全開口面積 は、キャリア13の全表面積に対して0.8%~20% とする。貫通孔19を通ってスラリーがウェーハ下面に も供給される。0.8%未満ではスラリーのウェーハ1 4下面への供給量が不充分で、下面にスクラッチが発生 する。20%を越えると、キャリア13自体の機械的強 度が不足してウェーハ14の保持が完全ではなく、ウェ ーハ14に割れが生じるおそれがある。貫通孔1個の開 口面積は例えば60 cm'以下が好適である。複数の貫 通孔はキャリア全面に対して均一に分散して形成する。 ラッピングには、FO等を含むスラリーを用いる。スク ラッチ、割れが生じない。



20

【特許請求の範囲】

【請求項1】 互いに平行に設けられた下定盤および上

これらの上定盤と下定盤との間に介在され、ウェーハを 保持するキャリアと、を備え、スラリーがキャリアの上 方から供給されるラッピング装置において、

上記キャリアに上下方向に貫通する貫通路を形成したラ ッピング装置。

【請求項2】 上記貫通路は、上記キャリアの表面に略 均一に分布して形成された複数の孔である請求項1に記 10 載のラッピング装置。

【請求項3】 上記孔は、キャリアの全表面積に対して 0.8~20%の開口面積を有する請求項2に記載のラ ッピング装置。

【発明の詳細な説明】

[0001]

【発明の属する技術分野】との発明はシリコンウェーハ などのラッピングに使用されるラッピング装置、特にウ ェーハ両面を同時にラッピングするラッピング装置の改 良に関する。

[0002]

[従来の技術] 従来のこの種のラッピング装置は、キャ リアにウェーハを挿入・保持し、その上方からスラリー をウェーハに供給しながら、ラッピングを行う構成であ った。すなわち、回転自在に設けた太陽ギヤとリングギ ヤとの間にキャリアを自転かつ公転自在に設け、このキ ャリアに保持したウェーハの表裏面(上下面)を上定盤 と下定盤とで押圧・摺接することによりラッピング加工 を施していた。そして、との場合、スラリーは上定盤に 形成した孔よりキャリア上面に供給していた。

[0003]

【発明が解決しようとする課題】しかしながら、このよ うな従来のラッピング装置にあっては、このキャリアに はウェーハを保持する穴以外には貫通孔が形成されてい ないので、スラリーがウェーハの下側に廻り込みにく い。すなわち、従来のラッピング装置では、ラップ加工 中、スラリーがキャリアの上方より供給されるため、ウ ェーハ上面にはスラリーが充分供給されるが、その下面 には供給されにくい。その結果、ウェーハ下面にスクラ ッチが発生し易いという課題が生じていた。

[0004]

【発明の目的】との発明は、ウェーハ下面のスクラッチ 発生をなくしたラッピング装置を提供することを、その 目的としている。また、との発明は、ラッピング加工で のウェーハの割れがないラッピング装置を提供すること を、その目的としている。

[0005]

【課題を解決するための手段】請求項1に記載の発明 は、互いに平行に設けられた下定盤および上定盤と、と れらの上定盤と下定盤との間に介在され、ウェーハを保 50 りに配設され、各キャリア13には4枚のシリコンウェ

持するキャリアと、を備え、スラリーがキャリアの上方 から供給されるラッピング装置において、上記キャリア に上下方向に貫通する貫通路を形成したラッピング装置

である。

【0006】請求項2に記載の発明は、上記貫通路は、 上記キャリアの表面に略均一に分布して形成された複数 の孔である請求項1 に記載のラッピング装置である。

【0007】請求項3に記載の発明は、上記孔は、キャ リアの全表面積に対して0.8~20%の開口面積を有 する請求項2に記載のラッピング装置である。

[8000]

【作用】請求項1に記載の発明では、ラップ加工時、ス ラリーがキャリアの上方から供給される。このスラリー は貫通路を通ってキャリアの下部に、すなわち保持する ウェーハの下面に対して供給される。この結果、ウェー ハ下面と下定盤との間に充分な量のスラリーを供給する ことができ、スクラッチの発生を完全に回避することが できる。

【0009】請求項2、請求項3に記載の発明では、ラ ップ加工時、スラリーがキャリアの上方から供給され る。とのスラリーは複数の孔を通って保持するウェーハ の下面に対して充分に供給される。よって、スクラッチ 発生は防止することができる。また、複数の孔の開口面 積を、キャリアの全表面積に対して0.8~20%の間 にしたため、キャリア自体の機械的強度を保持すること もできる。そして、キャリアに保持されたウェーハに割 れが生じることがない。例えば20%を越えて孔を形成 すると、キャリアの機械的強度不足の状態となって、キ ャリア自体がラッピング中に変形し、ウェーハに割れが 30 生じることがある。また、この値が0.8%未満である と、下面へのスラリーの供給量が充分ではなく、スクラ ッチの問題が生じるからである。ととに、キャリアの全 表面積とは、ウェーハ保持用の穴を含むキャリアの上面 全体の面積を言う。換言すると、キャリアの半径をrと し、全表面積をSとした場合、 $S = \pi r^{2}$ の関係にあ

[0010]

【発明の実施の形態】以下、この発明の一実施例を図面 を参照して説明する。図1~図3はこの発明に係るラッ 40 ピング装置の一実施例を示す図である。図4、図5は貫 通孔の開口面積(対キャリア全表面積比) とウェーハの 割れ、ウェーハへのスクラッチ発生との関係を示すグラ フである。

【0011】これらの図1~図3に示すように、この両 面ラッピング装置は、軸回りに回転自在に設けられた太 陽ギヤ11と、この軸と同軸的に回転自在に設けられた リングギヤ12と、これらの両ギヤ11,12に同時に 歯合して公転および自転する円形板状のキャリア13と を有している。キャリア13は複数個太陽ギヤ11の回

ーハ 1 4 がその穴に挿入されてそれぞれ保持されている。

【0012】各キャリア13の上下にはこれと平行に上定盤15および下定盤16が配設され、これらの上定盤15および下定盤16とキャリア13との間にスラリーを供給することにより、各ウェーハ14はその表裏面(上下面)がラッピングされることとなる。すなわち、上定盤15には複数の貫通路17が形成されており、これらの貫通路17より供給源からのスラリーが上定盤15の下面とキャリア13上面との間に供給されるよう構10成されている。なお、図2に示すように、これらの上定盤15および下定盤17の各ラップ面には溝18(例えば溝幅2mm、溝深さ10mm)が形成されている。

【0013】そして、上記構成に係るラッピング装置に あって、上記キャリア13にはその厚さ方向に(上下方 向に) とれを貫通する貫通孔19が複数個形成されてい る。とれらの貫通孔19の全開口面積は、キャリア13 の全表面積に対して0.8%~20%となるように設定 されている。0.8%未満ではスラリーのウェーハ14 下面への供給量が不充分であって、図5に示すように下 20 面にスクラッチが発生するからである。また、20%を 越えて貫通孔19を形成すると、キャリア13自体の機 械的強度が不足してウェーハ14の保持が完全ではな く、ウェーハ14に割れが生じるおそれがあるからであ る。図4には貫通孔19の開口面積とウェーハ14の割 れとの関係を示している。なお、貫通孔1個の開口面積 は例えば60cm'以下であることが好適である。ま た、複数の貫通孔はキャリア全面に対して均一に分散し て形成するものとする。ラッピングに使用するスラリー としては、公知のもの、例えば複合人造エメリ(FO) 等を含むスラリーが用いられる。

【0014】図4は、上記貫通孔19の全開口面積がキャリア13の全表面積に占める比率と、このキャリア13を用いたラッピングでのウェーハの割れ発生との関係を示す図である。このラッピングでは、鋳鉄製のキャリアを使用したラッピング装置で、ラッピング砥粒としては複合人造エメリ(FO#1200)を含むスラリーを\*

\*用いた。8インチ径のシリコンウェーハをラッピング し、その割れを目視で観察した。

【0015】図5は、上記キャリアの全開口面積がキャリアの全表面積に占める比率と、とのキャリアを用いたラッピングでのウェーハ下面のスクラッチ発生との関係を示す図である。具体的には、上記図4の場合と同じく、複合人造エメリ(FO#1200)をラッピング砥粒として鋳鉄製キャリアを用いて8インチウェーハをラッピングした。その結果としてのウェーハ裏面のスクラッチは目視で観察した。これらの図4、図5に示すように、キャリアに形成した貫通孔19の開口面積が0.8%未満ではスクラッチ発生が増加し、20%を越えるとウェーハの割れ発生率が高くなる。

#### [0016]

【発明の効果】との発明によれば、ラッピング加工においてウェーハ下面にスクラッチが発生し難い。また、ウェーハに割れが生じることもない。

#### 【図面の簡単な説明】

【図1】この発明の一実施例に係るラッピング装置の一 部を破断して示す斜視図である。

【図2】との発明の一実施例に係るラッピング装置を示す縦断面図である。

【図3】 この発明の一実施例に係るラッピング装置のキャリアを示す平面図である。


【図4】 この発明の一実施例に係るラッピング装置での キャリア貫通孔の開口面積とウェーハの割れとの関係を 示すグラフである。

【図5】との発明の一実施例に係るラッピング装置での キャリア貫通孔の開口面積とウェーハのスクラッチ発生 30 率との関係を示すグラフである。


#### 【符号の説明】


- 13 キャリア、
- 14 シリコンウェーハ、
- 15 上定盤、
- 16 下定盤、
- 17 貫通路。


[図2]




【図4】







【図3】



# フロントページの続き

(72)発明者 北村 芳樹 東京都千代田区大手町1丁目5番1号 三

東京都十代田区大手町1丁日5番1号 = 菱マテリアルシリコン株式会社内

(72)発明者 杉谷 和明

東京都千代田区大手町1丁目5番1号 三 菱マテリアルシリコン株式会社内